

Oil Field Environmental Incident Summary

Incident: 20140314100411

Date/Time of Notice: 03/14/2014 10:04

Responsible Party: RIM Operating, Inc

Well Operator: RIM OPERATING, INC.

Well Name:

Field Name: CUSTOMS

Well File #: 16044

Date Incident: 3/13/2014

Time Incident: 00:10

Facility ID Number:

County: BURKE

Twp: 163

Rng: 90

Sec: 13

Qtr: NW NW

Location Description:

Submitted By: Liz Ortiz

Received By:

Contact Person: Ken Read

5 Inverness Drive East

Englewood, CO 80112

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:

1 Mile

Distance Nearest Water Well:

1 Mile

Type of Incident Pipeline Leak

Release Contained in Dike Yes - Within Dike

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	5	Barrels	5	Barrels		

Brine

Other

Description of Other Released Contaminant:

Inspected:

Written Report Received:

Clean Up Concluded:

Risk Evaluation:

none

Areal Extent:

Potential Environmental Impacts:

none

Action Taken or Planned:

well was shut in and recycle line was repaired

Wastes Disposal Location: all oil was recovered by steaming and separating oil and water. Oil was placed in tank on location, water to Steamboat disposal well.

Agencies Involved:

Updates

Date: 3/14/2014 **Status:** Reviewed; Followup Required **Staff:** Stockdill, Scott

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

According to the incident summary, this spill remained on location. However, due to the vague reporting, followup is necessary.

Date: 3/17/2014 **Status:** Inspected **Staff:** O'Gorman, Brian

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Arrived on location at 15:05, 3/17/14. 47 degrees F, NE wind 5-10, overcast. Observed site and took photos. Walked the perimeter of the well site and did not observe any impacts off the well pad. It appeared as if a pipe (recycle line) located next to the pump jack had some repair work done recently as evidenced by a pile of soil (some impacted) next to the pipeline and a depression where soil had been replaced next to the pipe. Follow up with phone call to NDIC to document removal of impacted soil from well pad. Sign near tanks showed well to be Sorum 11-13H.